



**Fig. P5.72**

**5.72** A 1000-lb force is applied at point A of the cast-iron member shown. Knowing that the member has a diameter of 1.8 in., determine the normal and shearing stresses at point H located on the top surface of the member.