



Fig. P5.84 and P5.85

5.84 Three forces are applied to a W 10 × 33 rolled-steel shape as shown. Determine the normal and shearing stresses at points *a* and *b*.